








40 min







Tools needed (not supplied)



A		6x30	x24
B		6,5x27	x18
C		10x11	x18
D		4,2x45	x4
E		5x38	x12
F		4x30	x4
G		D39x20	x4




H		350mm	x3
J		11/5,8x6,5	x18
M		3x15	x12
K		758mm	x1
L		3,5x20	x8
N		D28x20,5	x6
P		M4x20	x6

①




A		6x30	x24
---	---	------	-----


②




B		6,5x27	x18
---	---	--------	-----


3



H-1		350mm	x3
-----	---	-------	----


H-2		350mm	x3
J		11/5,8x6,5	x18

4





D		4,2x45	x4
---	---	--------	----

5







G		D39x20	x4
F		4x30	x4

6








K		758mm	x1
---	--	-------	----

7






C		10x11	x6
---	--	-------	----

8



L		3,5x20	x8
---	--	--------	----




9



3x

C		10x11	x12
---	---	-------	-----


10




3x


E		5x38	x12
---	---	------	-----

11




3x




H-3		350mm	x3
-----	---	-------	----

H-4		350mm	x3
M		3x15	x12

12



3x



N		D28x20,5	x6
P		M4x20	x6

13

3x

