





A		8x40	x68
B		8x30	x6
C		6,3x105	x6
D		M6x100	x4
E		M6x10x13	x4
F		7x50	x4
G		7x60	x4
H		D35	x4
J		5x38	x4

K		D15x18	x10
L		D13	x2
M		D4x13	x4
N		D35x12	x2
P		3,5x40	x28
Q		71x30x3	x2
R		4mm	x1
S		GLUE	x1


①




②



③




4




G		7x60	x4
---	---	------	----

5





H		D35	x1
---	---	-----	----

6



H		D35	x1
---	---	-----	----



7



D		M6x100	x2
E		M6x10x13	x2


K		D15x18	x2
L		D13	x2

8




D		M6x100	x2
E		M6x10x13	x2
K		D15x18	x2


9




A		8x40	x12
---	---	------	-----

10




C		6,3x105	x2
K		D15x18	x2

11




12




F		7x50	x4
M		D4x13	x4


13




14



15




16




P		3,5x40	x10
Q		71x30x3	x2

17



NB!



P		3,5x40	x18
Q		71x30x3	x2