










**A****B**

Tools needed (not supplied)




60 min




A		8x40	x42
B		10x40	x4
C		M6x65	x4
D		D6x10x13	x4
E		6,3x60	x9
F		6,3x105	x2
G		7x50	x4
H		7x60	x4
J		55/12,5x5	x5
K		D35	x4
L		7x24	x4
M		D15x9,5	x4
N		4x20	x4
P		3,5x35	x38
Q		D13	x9
R		D20	x4
S		D4x13	x4
T		D5x8	x2
U		D8x13	x5
V		D15x18	x15
X		D35x12	x4
Y		D24x3	x8
Z		4mm	x1

1





A		8x40	x42
---	---	------	-----

2




2x




H		7x60	x4
---	---	------	----


3




4a



4b




5a



A

M		D15x9,5	x4
---	---	---------	----

5b





B

M		D15x9,5	x4
---	---	---------	----

6a


A



C		M6x65	x2
D		M6x10x13	x2
E		6,3x60	x2


6b

B




C		M6x65	x2
D		M6x10x13	x2
E		6,3x60	x2

7a




C		M6x65	x2
D		M6x10x13	x2


7b




C		M6x65	x2
D		M6x10x13	x2


8



F		6,3x105	x2
---	--	---------	----

9




E		6,3x60	x2
---	---	--------	----


10

A




1.




2.



3.






4mm




B		10x40	x4
E		6,3x60	x4

11



N		4x20	x4
---	---	------	----

12



P



3,5x35


x8

13




4mm

B



A



G



7x50

x4





S




D4x13



x4

14





E		6,3x60	x1
J		55/12,5x5	x5

15



P		3,5x35	x30
---	---	--------	-----

16



Q		D13	x9
R		D20	x4

T		D5x8	x2
U		D8x13	x5
V		D15x18	x15